

DAFTAR GAMBAR

No.	Judul	Halaman
Gambar 2.1	Contoh Analisis FMEA	21
Gambar 3.1	Diagram Alir Penelitian	30
Gambar 4.1	Struktur Organisasi PT Kertas Leces (Persero)	33
Gambar 4.2	Proses Pembuatan Kertas	34
Gambar 4.3	<i>Flow Process Mapping</i>	38
Gambar 4.4	Diagram Pareto <i>Waste Defect</i>	50
Gambar 4.5	Diagram Pareto <i>Waste Waiting</i>	52
Gambar 4.6	Diagram Pareto <i>Waste Inventory</i>	53
Gambar 4.7	Diagram Pareto <i>Waste Excess Transportation</i>	54
Gambar 4.8	Diagram Sebab Akibat Gramatur Menyimpang	56
Gambar 4.9	Diagram Sebab Akibat Kertas Pecah	58
Gambar 4.10	Diagram Sebab Akibat Kertas Gembos	60
Gambar 4.11	Diagram Sebab Akibat Potongan Kurang Rapi	62
Gambar 4.12	Diagram Sebab Akibat <i>Waiting PO</i>	63
Gambar 4.13	Diagram Sebab Akibat <i>Waiting PLTU</i>	65
Gambar 4.14	Diagram Sebab Akibat <i>Inventory Raw Material</i>	66
Gambar 4.15	Diagram Sebab Akibat Masalah <i>Rework</i>	69
Gambar 4.16	Diagram Sebab Akibat <i>Waste Transportasi Finishing</i>	71
Gambar 4.17	Diagram Sebab Akibat <i>Waste Transportasi Gudang</i>	72
Gambar 4.18	Diagram Sebab Akibat <i>Waste Transportasi Hydrapulper</i>	74
Gambar 4.19	Usulan Perbaikan Tangga Berjalan	80
Gambar 4.20	Ukuran Tangga Berjalan	82
Gambar 4.21	Label Peringatan Penggantian Bentangan	84