

DAFTAR GAMBAR

No.	Judul	Halaman
Gambar 1.1a	Cacat Jenis Kotor Hitam	2
Gambar 1.1b	Cacat Jenis Lengketan Sisa Material	2
Gambar 1.2	Rasio Cacat Produk Botol Ukuran 19 Liter Bulan September 2014–April 2015	3
Gambar 2.1	Lambang Operasi	12
Gambar 2.2	Lambang Pemeriksaan	12
Gambar 2.3	Lambang Aktivitas Gabungan	13
Gambar 2.4	Lambang Penyimpanan	13
Gambar 2.5	Sketsa Peta Proses Operasi (OPC)	14
Gambar 2.6	Contoh Diagram Pareto	23
Gambar 2.7	Contoh <i>Control Chart</i>	24
Gambar 2.8	Contoh <i>Checklist</i>	26
Gambar 3.1	Diagram Alir Penelitian	35
Gambar 4.1	Tampak Depan PT. Berlina Tbk	38
Gambar 4.2	Letak PT. Berlina Tbk	38
Gambar 4.3	Polikarbonat Murni	44
Gambar 4.4	Polikarbonat <i>Regrind</i>	45
Gambar 4.5	<i>Master Batch</i>	46
Gambar 4.6	Peta Proses Operasi Produksi Botol Ukuran 19 Liter	47
Gambar 4.7	Proses <i>Mixing</i>	48
Gambar 4.8	Proses <i>Dehumidifying</i>	48
Gambar 4.9	<i>Barel</i> Mesin <i>Blow Moulding</i>	49
Gambar 4.10	Ruang Pemroses pada Mesin <i>Blow Moulding</i>	50
Gambar 4.11	Ruang Pemroses pada Proses <i>Deflashing</i>	51
Gambar 4.12	Proses <i>Anealling</i>	52
Gambar 4.13	Proses Pembersihan Serpihan Plastik	45
Gambar 4.14	Proses Inspeksi I	53
Gambar 4.15	Proses <i>Labelling</i>	53
Gambar 4.16	Proses <i>Packaging</i>	54
Gambar 4.17	Proses Inspeksi II	54
Gambar 4.18	Produk Setengah Jadi	55

Gambar 4.19	Produk Jadi	55
Gambar 4.20	Jenis Cacat <i>Air Trapped</i>	56
Gambar 4.21	Diagram Pareto Jenis dan Jumlah Cacat Proses <i>Blow Moulding</i>	63
Gambar 4.22	Peta Kontrol P Cacat Kotor Hitam	66
Gambar 4.23	Peta Kontrol P Cacat Lengketan Sisa Material	68
Gambar 4.24	Peta Kontrol P Cacat <i>Neck Amandel</i>	70
Gambar 4.25	<i>Root Cause Analysis</i> Cacat Kotor Hitam	75
Gambar 4.26	<i>Root Cause Analysis</i> Cacat Lengketan Sisa Material	76
Gambar 4.27	<i>Root Cause Analysis</i> Cacat <i>Neck Amandel</i>	78
Gambar 4.28	Letak Pemberian <i>Lock Nut</i> pada Alat Pemotong Afval	86
Gambar 4.29a	Celah antara <i>Sliding</i> dan <i>Sliding House</i> Terisi Kerak	87
Gambar 4.29b	Celah antara <i>Sliding</i> dan <i>Sliding House</i> Tidak Terisi Kerak	88

